Map ID MAP FINDINGS

Direction Distance

Distance Elevation Site EDR ID Number Database(s) EPA ID Number

625 ROADWAY NY Spills S122877768
ENE AVE Z AND E 6TH ST N/A

ENE AVE Z AND E 6TH ST 1/2-1 BROOKLYN, NY

0.926 mi. 4890 ft.

Relative: SPILLS:
Higher Name: ROADWAY

 Actual:
 Address:
 AVE Z AND E 6TH ST

 11 ft.
 City,State,Zip:
 BROOKLYN, NY

 Spill Number/Closed Date:
 1806756 / 2018-09-27

 Facility ID:
 1806756

 Facility Type:
 ER

 DER Facility ID:
 530340

 Site ID:
 577496

 DEC Region:
 2

Spill Cause: Equipment Failure

Spill Class: C3 2401 SWIS: Spill Date: 2018-09-25 Investigator: **HSSEKHON** Referred To: Not reported Reported to Dept: 2018-09-25 CID: Not reported Water Affected: Not reported

Spill Source: Institutional, Educational, Gov., Other

Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0

Date Entered In Computer: 2018-09-25 Spill Record Last Update: 2018-09-27

Spiller Name: ANDREW HASTINGS
Spiller Company: NYC DEP TRUCK
Spiller Address: AVE Z AND E 6TH ST

Spiller Company: 999

Contact Name: ANDREW HASTINGS

DEC Memo: "5-10 gallons of hydraulic oil spilled to the pavement due to equipment failure. Sanitation on site doing the clean up. 5/26-

Sekhon Spoke with notifier, Clean up was done yesterday. Spill

closed."

Remarks: "5-10 gallons to roadway, c/u pending"

All Materials:

Site ID: 577496 Operable Unit ID: 1325265 Operable Unit: 01 Material ID: 2333845 0010 Material Code: Material Name: hydraulic oil Case No .: Not reported Material FA: Petroleum Quantity: 10.00 Units: G

Recovered: Not reported Oxygenate: Not reported